

Inspection Report



Facility: Livingston Lakes Condo

Address: 15098 Palmer Lake Circle,
Naples, FL 34109

Customer: Cardinal Management

Address: c/o Livingston Lakes Condo, 15090
Naples, FL 34109

Prepared By:

Crowther Roofing & Sheet Metal of FL, Inc.
2543 Rockfill Road,
Ft. Myers, Florida 33916

Tel: 239-337-1600 **Fax:** (239) 332-0939

Crowther.net



Inspection Date: Friday, June 13, 2025

Inspection Report

Livingston Lakes Condo, Naples, FL

Work Order #: 13028

Inspection Date: 06/13/2025

Cardinal Management

June 26, 2025

c/o Livingston Lakes

livingstonlakes@cmgflorida.com

15090 Palmer Lakes Circle

Naples, FL 34109

Attn: Pamela Peterson

Re.: **Inspection Report (2 of 3) for Livingston Lakes**

Dear Pamela,

We would like to inform you that the 2nd of 3 RoofCheck Inspections has been completed. Enclosed is our report for your records. We also performed routine preventative maintenance called for in our agreement.

The inspections and preventative maintenance are key parts of minimizing roof leaks and maximizing the serviceability of your roof.

Thank you for your business. Please call if you have any questions on this report or whenever we may be of service. Our Service Department number is (239) 337-1600.

Sincerely yours,

Nate Wilder

(239) 272-9079

RoofCheck[™] Survey & Analysis
Crowther

Inspection Report

Livingston Lakes Condo, Naples, FL

Work Order #: 13028

Inspection Date: 06/13/2025



Building 15161
Building Identification



Building 15161: Surface Overview
The roof surface appears to be in good, maintainable condition at this time.



Building 15161: Appearance Overview
The roof appearance is in good, maintainable condition.



Building 15161: Surface Overview
The roof surface appears to be in good, maintainable condition at this time.

Inspection Report

Livingston Lakes Condo, Naples, FL

Work Order #: 13028

Inspection Date: 06/13/2025



Building 15161: Ridge Tiles

Ridge tiles appear to be in good condition.



Building 15161: Valley

The valley tiles appear to be in good condition.



Building 15161: Identified Cracked Roof Tiles

Cracked roof tiles can allow premature underlayment deterioration from excessive UV exposure.



Building 15161: Repaired Cracked Roof Tiles

The cracked roof tiles were repaired with Titebond sealant.

Inspection Report

Livingston Lakes Condo, Naples, FL

Work Order #: 13028

Inspection Date: 06/13/2025



Building 15161: Identified Cracked Roof Tiles
Cracked roof tiles can allow premature underlayment deterioration from excessive UV exposure.



Building 15161: Repaired Cracked Roof Tiles
The cracked roof tiles were repaired with Titebond sealant.



Building 15161: Identified Cracked Roof Tiles
Cracked roof tiles can allow premature underlayment deterioration from excessive UV exposure.



Building 15161: Repaired Cracked Roof Tiles
The cracked roof tiles were repaired with Titebond sealant.

Inspection Report

Livingston Lakes Condo, Naples, FL

Work Order #: 13028

Inspection Date: 06/13/2025



Building 15161: Displaced/Missing Roof Tile

Displaced or missing roof tiles can allow premature underlayment deterioration from excessive UV exposure and potential water intrusion.



Building 15161: Repaired Displaced/Missing Roof Tile

Replaced and secured the missing roof tile.



Building 15161: Roof Vents

Roof vents appear to be in good condition.



Building 15161: Roof Vents

Roof vents appear to be in good condition.

Inspection Report

Livingston Lakes Condo, Naples, FL

Work Order #: 13028

Inspection Date: 06/13/2025



Building 15161: Lead Boots
Lead boots appear to be in good condition.



Building 15161: Lead Boots
Lead boots appear to be in good condition.



Building 15161: Gutters
The gutters appear to be in good condition.



Building 15161: Gutters
The gutters appear to be in good condition.

Inspection Report

Livingston Lakes Condo, Naples, FL

Work Order #: 13028

Inspection Date: 06/13/2025



Building 15161: Surface Overview - Lower Roof
The roof surface appears to be in good, maintainable condition at this time.



Building 15161: Appearance Overview - Lower Roof
The roof appearance is in good, maintainable condition.



Building 15161: Wall
The walls appear to be in good condition.



Building 15161: Counter Flashings
The counter flashing appears to be in good condition.

Inspection Report

Livingston Lakes Condo, Naples, FL

Work Order #: 13028

Inspection Date: 06/13/2025



Building 15161: Appearance Overview - Lower Roof
The roof appearance is in good, maintainable condition.



Building 15161: Surface Overview - Lower Roof
The roof surface appears to be in good, maintainable condition at this time.



Building 15161: Identified Cracked Roof Tiles
Cracked roof tiles can allow premature underlayment deterioration from excessive UV exposure.



Building 15161: Repaired Cracked Roof Tiles
The cracked roof tiles were repaired with Titebond sealant.

Inspection Report

Livingston Lakes Condo, Naples, FL

Work Order #: 13028

Inspection Date: 06/13/2025



Building 15161: Identified Cracked Roof Tiles
Cracked roof tiles can allow premature underlayment deterioration from excessive UV exposure.



Building 15161: Repaired Cracked Roof Tiles
The cracked roof tiles were repaired with Titebond sealant.



Building 15161: Identified Cracked Roof Tiles
Cracked roof tiles can allow premature underlayment deterioration from excessive UV exposure.



Building 15161: Repaired Cracked Roof Tiles
The cracked roof tiles were repaired with Titebond sealant.

Inspection Report

Livingston Lakes Condo, Naples, FL

Work Order #: 13028

Inspection Date: 06/13/2025



Building 15161: Identified Cracked Roof Tiles
Cracked roof tiles can allow premature underlayment deterioration from excessive UV exposure.



Building 15161: Repaired Cracked Roof Tiles
The cracked roof tiles were repaired with Titebond sealant.



Building 15161: Downspouts
The downspouts appear to be in good condition.



Building 15161: Downspouts
The downspouts appear to be in good condition.

Inspection Report

Livingston Lakes Condo, Naples, FL

Work Order #: 13028

Inspection Date: 06/13/2025



Building 15165
Building Identification



Building 15165: Surface Overview
The roof surface appears to be in good, maintainable condition at this time.



Building 15165: Appearance Overview
The roof appearance is in good, maintainable condition.



Building 15165: Surface Overview
The roof surface appears to be in good, maintainable condition at this time.

Inspection Report

Livingston Lakes Condo, Naples, FL

Work Order #: 13028

Inspection Date: 06/13/2025



Building 15165: Ridge Tiles

Ridge tiles appear to be in good condition.



Building 15165: Valley

The valley tiles appear to be in good condition.



Building 15165: Displaced/Missing Roof Tile

Displaced or missing roof tiles can allow premature underlayment deterioration from excessive UV exposure and potential water intrusion.



Building 15165: Repaired Displaced/Missing Roof Tile

Replaced and secured the missing roof tile.

Inspection Report

Livingston Lakes Condo, Naples, FL

Work Order #: 13028

Inspection Date: 06/13/2025



Building 15165: Identified Cracked Roof Tiles

Cracked roof tiles can allow premature underlayment deterioration from excessive UV exposure.



Building 15165: Repaired Cracked Roof Tiles

The cracked roof tiles were repaired with Titebond sealant.



Building 15165: Displaced/Missing Roof Tile

Displaced or missing roof tiles can allow premature underlayment deterioration from excessive UV exposure and potential water intrusion.



Building 15165: Repaired Displaced/Missing Roof Tile

Replaced and secured the missing roof tile.

Inspection Report

Livingston Lakes Condo, Naples, FL

Work Order #: 13028

Inspection Date: 06/13/2025



Building 15165: Identified Cracked Roof Tiles
Cracked roof tiles can allow premature underlayment deterioration from excessive UV exposure.



Building 15165: Repaired Cracked Roof Tiles
The cracked roof tiles were repaired with Titebond sealant.



Building 15165: Identified Cracked Roof Tiles
Cracked roof tiles can allow premature underlayment deterioration from excessive UV exposure.



Building 15165: Repaired Cracked Roof Tiles
The cracked roof tiles were repaired with Titebond sealant.

Inspection Report

Livingston Lakes Condo, Naples, FL

Work Order #: 13028

Inspection Date: 06/13/2025



Building 15165: Displaced/Missing Roof Tile

Displaced or missing roof tiles can allow premature underlayment deterioration from excessive UV exposure and potential water intrusion.




Building 15165: Repaired Displaced/Missing Roof Tile

Replaced and secured the missing roof tile.



Building 15165: Identified Cracked Roof Tiles

Cracked roof tiles can allow premature underlayment deterioration from excessive UV exposure.



Building 15165: Repaired Cracked Roof Tiles

The cracked roof tiles were repaired with Titebond sealant.

Inspection Report

Livingston Lakes Condo, Naples, FL

Work Order #: 13028

Inspection Date: 06/13/2025



Building 15165: Identified Cracked Roof Tiles

Cracked roof tiles can allow premature underlayment deterioration from excessive UV exposure.



Building 15165: Repaired Cracked Roof Tiles

The cracked roof tiles were repaired with Titebond sealant.



Building 15165: Identified Cracked Roof Tiles

Cracked roof tiles can allow premature underlayment deterioration from excessive UV exposure.



Building 15165: Repaired Cracked Roof Tiles

The cracked roof tiles were repaired with Titebond sealant.

Inspection Report

Livingston Lakes Condo, Naples, FL

Work Order #: 13028

Inspection Date: 06/13/2025



Building 15165: Roof Vents
Roof vents appear to be in good condition.



Building 15165: Roof Vents
Roof vents appear to be in good condition.



Building 15165: Lead Boots
Lead boots appear to be in good condition.



Building 15165: Lead Boots
Lead boots appear to be in good condition.

Inspection Report

Livingston Lakes Condo, Naples, FL

Work Order #: 13028

Inspection Date: 06/13/2025



Building 15165: Gutters

The gutters appear to be in good condition.



Building 15165: Gutters

The gutters appear to be in good condition.



Building 15165: Surface Overview - Lower Roof

The roof surface appears to be in good, maintainable condition at this time.



Building 15165: Appearance Overview - Lower Roof

The roof appearance is in good, maintainable condition.

Inspection Report

Livingston Lakes Condo, Naples, FL

Work Order #: 13028

Inspection Date: 06/13/2025



Building 15165: Wall

The walls appear to be in good condition.



Building 15165: Downspout- missing

Downspout is missing. The painting company that is painting the exteriors in Livingston Lakes has the missing downspouts.



Building 15165: Surface Overview - Lower Roof

The roof surface appears to be in good, maintainable condition at this time.



Building 15165: Appearance Overview - Lower Roof

The roof appearance is in good, maintainable condition.

Inspection Report

Livingston Lakes Condo, Naples, FL

Work Order #: 13028

Inspection Date: 06/13/2025



Building 15165: Wall

The walls appear to be in good condition.



Building 15165: Downspouts

The downspouts appear to be in good condition.



Building 15169

Building Identification



Building 15169: Surface Overview

The roof surface appears to be in good, maintainable condition at this time.

Inspection Report

Livingston Lakes Condo, Naples, FL

Work Order #: 13028

Inspection Date: 06/13/2025



Building 15169: Appearance Overview
The roof appearance is in good, maintainable condition.



Building 15169: Appearance Overview
The roof appearance is in good, maintainable condition.



Building 15169: Ridge Tiles
Ridge tiles appear to be in good condition.



Building 15169: Valley
The valley tiles appear to be in good condition.

Inspection Report

Livingston Lakes Condo, Naples, FL

Work Order #: 13028

Inspection Date: 06/13/2025



Building 15169: Displaced/Missing Roof Tile

Displaced or missing roof tiles can allow premature underlayment deterioration from excessive UV exposure and potential water intrusion.



Building 15169: Repaired Displaced/Missing Roof Tile

Replaced and secured the missing roof tile.



Building 15169: Roof Vents

Roof vents appear to be in good condition.



Building 15169: Roof Vents

Roof vents appear to be in good condition.

Inspection Report

Livingston Lakes Condo, Naples, FL

Work Order #: 13028

Inspection Date: 06/13/2025



Building 15169: Lead Boots

Lead boots appear to be in good condition.



Building 15169: Lead Boots

Lead boots appear to be in good condition.



Building 15169: Gutters

The gutters appear to be in good condition.



Building 15169: Gutters

The gutters appear to be in good condition.

Inspection Report

Livingston Lakes Condo, Naples, FL

Work Order #: 13028

Inspection Date: 06/13/2025



Building 15169: Surface Overview - Lower Roof
The roof surface appears to be in good, maintainable condition at this time.



Building 15169: Appearance Overview - Lower Roof
The roof appearance is in good, maintainable condition.



Building 15169: Identified Cracked Roof Tiles
Cracked roof tiles can allow premature underlayment deterioration from excessive UV exposure.



Building 15169: Repaired Cracked Roof Tiles
The cracked roof tiles were repaired with Titebond sealant.

Inspection Report

Livingston Lakes Condo, Naples, FL

Work Order #: 13028

Inspection Date: 06/13/2025



Building 15169: Displaced/Missing Roof Tile

Displaced or missing roof tiles can allow premature underlayment deterioration from excessive UV exposure and potential water intrusion.



Building 15169: Repaired Displaced/Missing Roof Tile

Replaced and secured the missing roof tile.



Building 15169: Identified Cracked Roof Tiles

Cracked roof tiles can allow premature underlayment deterioration from excessive UV exposure.



Building 15169: Repaired Cracked Roof Tiles

The cracked roof tiles were repaired with Titebond sealant.

Inspection Report

Livingston Lakes Condo, Naples, FL

Work Order #: 13028

Inspection Date: 06/13/2025



Building 15169: Wall

The walls appear to be in good condition.



Building 15169: Counter Flashings

The counter flashing appears to be in good condition.



Building 15169: Surface Overview - Lower Roof

The roof surface appears to be in good, maintainable condition at this time.



Building 15169: Downspout- missing

Downspout is missing. The painting company that is painting the exteriors in Livingston Lakes has the missing downspouts.

Inspection Report

Livingston Lakes Condo, Naples, FL

Work Order #: 13028

Inspection Date: 06/13/2025



Building 15169: Identified Cracked Roof Tiles
Cracked roof tiles can allow premature underlayment deterioration from excessive UV exposure.



Building 15169: Repaired Cracked Roof Tiles
The cracked roof tiles were repaired with Titebond sealant.



Building 15169: Identified Cracked Roof Tiles
Cracked roof tiles can allow premature underlayment deterioration from excessive UV exposure.



Building 15169: Repaired Cracked Roof Tiles
The cracked roof tiles were repaired with Titebond sealant.

Inspection Report

Livingston Lakes Condo, Naples, FL

Work Order #: 13028

Inspection Date: 06/13/2025



Building 15169: Identified Cracked Roof Tiles
Cracked roof tiles can allow premature underlayment deterioration from excessive UV exposure.



Building 15169: Repaired Cracked Roof Tiles
The cracked roof tiles were repaired with Titebond sealant.



Building 15169: Downspouts
The downspouts appear to be in good condition.



Building 15169: Downspouts
The downspouts appear to be in good condition.

Inspection Report

Livingston Lakes Condo, Naples, FL

Work Order #: 13028

Inspection Date: 06/13/2025



Building 15173
Building Identification



Building 15173: Surface Overview
The roof surface appears to be in good, maintainable condition at this time.



Building 15173: Appearance Overview
The roof appearance is in good, maintainable condition.



Building 15173: Appearance Overview
The roof appearance is in good, maintainable condition.

Inspection Report

Livingston Lakes Condo, Naples, FL

Work Order #: 13028

Inspection Date: 06/13/2025



Building 15173: Ridge Tiles

Ridge tiles appear to be in good condition.



Building 15173: Valley

The valley tiles appear to be in good condition.



Building 15173: Identified Cracked Roof Tiles

Cracked roof tiles can allow premature underlayment deterioration from excessive UV exposure.



Building 15173: Repaired Cracked Roof Tiles

The cracked roof tiles were repaired with Titebond sealant.

Inspection Report

Livingston Lakes Condo, Naples, FL

Work Order #: 13028

Inspection Date: 06/13/2025



Building 15173: Displaced/Missing Roof Tile

Displaced or missing roof tiles can allow premature underlayment deterioration from excessive UV exposure and potential water intrusion.



Building 15173: Repaired Displaced/Missing Roof Tile

Replaced and secured the missing roof tile.



Building 15173: Identified Cracked Roof Tiles

Cracked roof tiles can allow premature underlayment deterioration from excessive UV exposure.



Building 15173: Repaired Cracked Roof Tiles

The cracked roof tiles were repaired with Titebond sealant.

Inspection Report

Livingston Lakes Condo, Naples, FL

Work Order #: 13028

Inspection Date: 06/13/2025



Building 15173: Displaced/Missing Roof Tile

Displaced or missing roof tiles can allow premature underlayment deterioration from excessive UV exposure and potential water intrusion.



Building 15173: Repaired Displaced/Missing Roof Tile

Replaced and secured the missing roof tile.



Building 15173: Identified Cracked Roof Tiles

Cracked roof tiles can allow premature underlayment deterioration from excessive UV exposure.



Building 15173: Repaired Cracked Roof Tiles

The cracked roof tiles were repaired with Titebond sealant.

Inspection Report

Livingston Lakes Condo, Naples, FL

Work Order #: 13028

Inspection Date: 06/13/2025



Building 15173: Identified Cracked Roof Tiles
Cracked roof tiles can allow premature underlayment deterioration from excessive UV exposure.



Building 15173: Repaired Cracked Roof Tiles
The cracked roof tiles were repaired with Titebond sealant.



Building 15173: Roof Vents
Roof vents appear to be in good condition.



Building 15173: Roof Vents
Roof vents appear to be in good condition.

Inspection Report

Livingston Lakes Condo, Naples, FL

Work Order #: 13028

Inspection Date: 06/13/2025



Building 15173: Lead Boots
Lead boots appear to be in good condition.



Building 15173: Lead Boots
Lead boots appear to be in good condition.



Building 15173: Gutters
The gutters appear to be in good condition.



Building 15173: Gutters
The gutters appear to be in good condition.

Inspection Report

Livingston Lakes Condo, Naples, FL

Work Order #: 13028

Inspection Date: 06/13/2025



Building 15173: Surface Overview - Lower Roof
The roof surface appears to be in good, maintainable condition at this time.



Building 15173: Appearance Overview - Lower Roof
The roof appearance is in good, maintainable condition.



Building 15173: Surface Overview - Lower Roof
The roof surface appears to be in good, maintainable condition at this time.



Building 15173: Appearance Overview - Lower Roof
The roof appearance is in good, maintainable condition.

Inspection Report

Livingston Lakes Condo, Naples, FL

Work Order #: 13028

Inspection Date: 06/13/2025



Building 15173: Identified Cracked Roof Tiles
Cracked roof tiles can allow premature underlayment deterioration from excessive UV exposure.



Building 15173: Repaired Cracked Roof Tiles
The cracked roof tiles were repaired with Titebond sealant.



Building 15173: Identified Cracked Roof Tiles
Cracked roof tiles can allow premature underlayment deterioration from excessive UV exposure.



Building 15173: Repaired Cracked Roof Tiles
The cracked roof tiles were repaired with Titebond sealant.

Inspection Report

Livingston Lakes Condo, Naples, FL

Work Order #: 13028

Inspection Date: 06/13/2025



Building 15173: Identified Cracked Roof Tiles
Cracked roof tiles can allow premature underlayment deterioration from excessive UV exposure.



Building 15173: Repaired Cracked Roof Tiles
The cracked roof tiles were repaired with Titebond sealant.



Building 15173: Identified Cracked Roof Tiles
Cracked roof tiles can allow premature underlayment deterioration from excessive UV exposure.



Building 15173: Repaired Cracked Roof Tiles
The cracked roof tiles were repaired with Titebond sealant.

Inspection Report

Livingston Lakes Condo, Naples, FL

Work Order #: 13028

Inspection Date: 06/13/2025



Building 15173: Identified Cracked Roof Tiles
Cracked roof tiles can allow premature underlayment deterioration from excessive UV exposure.



Building 15173: Repaired Cracked Roof Tiles
The cracked roof tiles were repaired with Titebond sealant.



Building 15173: Identified Cracked Roof Tiles
Cracked roof tiles can allow premature underlayment deterioration from excessive UV exposure.



Building 15173: Repaired Cracked Roof Tiles
The cracked roof tiles were repaired with Titebond sealant.

Inspection Report

Livingston Lakes Condo, Naples, FL

Work Order #: 13028

Inspection Date: 06/13/2025



Building 15173: Identified Cracked Roof Tiles
Cracked roof tiles can allow premature underlayment deterioration from excessive UV exposure.



Building 15173: Repaired Cracked Roof Tiles
The cracked roof tiles were repaired with Titebond sealant.



Building 15173: Downspouts
The downspouts appear to be in good condition.



Building 15173: Downspouts
The downspouts appear to be in good condition.

Inspection Report

Livingston Lakes Condo, Naples, FL

Work Order #: 13028

Inspection Date: 06/13/2025



Building 15177
Building Identification



Building 15177: Surface Overview
The roof surface appears to be in good, maintainable condition at this time.



Building 15177: Appearance Overview
The roof appearance is in good, maintainable condition.



Building 15177: Surface Overview
The roof surface appears to be in good, maintainable condition at this time.

Inspection Report

Livingston Lakes Condo, Naples, FL

Work Order #: 13028

Inspection Date: 06/13/2025



Building 15177: Ridge Tiles

Ridge tiles appear to be in good condition.



Building 15177: Valley

The valley tiles appear to be in good condition.



Building 15177: Identified Cracked Roof Tiles

Cracked roof tiles can allow premature underlayment deterioration from excessive UV exposure.



Building 15177: Repaired Cracked Roof Tiles

The cracked roof tiles were repaired with Titebond sealant.

Inspection Report

Livingston Lakes Condo, Naples, FL

Work Order #: 13028

Inspection Date: 06/13/2025



Building 15177: Identified Cracked Roof Tiles
Cracked roof tiles can allow premature underlayment deterioration from excessive UV exposure.



Building 15177: Repaired Cracked Roof Tiles
The cracked roof tiles were repaired with Titebond sealant.



Building 15177: Identified Cracked Roof Tiles
Cracked roof tiles can allow premature underlayment deterioration from excessive UV exposure.



Building 15177: Repaired Cracked Roof Tiles
The cracked roof tiles were repaired with Titebond sealant.

Inspection Report

Livingston Lakes Condo, Naples, FL

Work Order #: 13028

Inspection Date: 06/13/2025



Building 15177: Identified Cracked Roof Tiles
Cracked roof tiles can allow premature underlayment deterioration from excessive UV exposure.



Building 15177: Repaired Cracked Roof Tiles
The cracked roof tiles were repaired with Titebond sealant.



Building 15177: Displaced/Missing Roof Tile
Displaced or missing roof tiles can allow premature underlayment deterioration from excessive UV exposure and potential water intrusion.



Building 15177: Repaired Displaced/Missing Roof Tile
Replaced and secured the missing roof tile.

Inspection Report

Livingston Lakes Condo, Naples, FL

Work Order #: 13028

Inspection Date: 06/13/2025



Building 15177: Identified Cracked Roof Tiles

Cracked roof tiles can allow premature underlayment deterioration from excessive UV exposure.



Building 15177: Repaired Cracked Roof Tiles

The cracked roof tiles were repaired with Titebond sealant.



Building 15177: Displaced/Missing Roof Tile

Displaced or missing roof tiles can allow premature underlayment deterioration from excessive UV exposure and potential water intrusion.



Building 15177: Repaired Displaced/Missing Roof Tile

Replaced and secured the missing roof tile.

Inspection Report

Livingston Lakes Condo, Naples, FL

Work Order #: 13028

Inspection Date: 06/13/2025



Building 15177: Identified Cracked Roof Tiles
Cracked roof tiles can allow premature underlayment deterioration from excessive UV exposure.



Building 15177: Repaired Cracked Roof Tiles
The cracked roof tiles were repaired with Titebond sealant.



Building 15177: Roof Vents
Roof vents appear to be in good condition.



Building 15177: Roof Vents
Roof vents appear to be in good condition.

Inspection Report

Livingston Lakes Condo, Naples, FL

Work Order #: 13028

Inspection Date: 06/13/2025



Building 15177: Lead Boots
Lead boots appear to be in good condition.



Building 15177: Lead Boots
Lead boots appear to be in good condition.



Building 15177: Gutters
The gutters appear to be in good condition.



Building 15177: Gutters
The gutters appear to be in good condition.

Inspection Report

Livingston Lakes Condo, Naples, FL

Work Order #: 13028

Inspection Date: 06/13/2025



Building 15177: Surface Overview - Lower Roof
The roof surface appears to be in good, maintainable condition at this time.



Building 15177: Appearance Overview - Lower Roof
The roof appearance is in good, maintainable condition.



Building 15177: Surface Overview - Lower Roof
The roof surface appears to be in good, maintainable condition at this time.



Building 15177: Appearance Overview - Lower Roof
The roof appearance is in good, maintainable condition.

Inspection Report

Livingston Lakes Condo, Naples, FL

Work Order #: 13028

Inspection Date: 06/13/2025



Building 15177: Identified Cracked Roof Tiles
Cracked roof tiles can allow premature underlayment deterioration from excessive UV exposure.



Building 15177: Repaired Cracked Roof Tiles
The cracked roof tiles were repaired with Titebond sealant.



Building 15177: Identified Cracked Roof Tiles
Cracked roof tiles can allow premature underlayment deterioration from excessive UV exposure.



Building 15177: Repaired Cracked Roof Tiles
The cracked roof tiles were repaired with Titebond sealant.

Inspection Report

Livingston Lakes Condo, Naples, FL

Work Order #: 13028

Inspection Date: 06/13/2025



Building 15177: Identified Cracked Roof Tiles
Cracked roof tiles can allow premature underlayment deterioration from excessive UV exposure.



Building 15177: Repaired Cracked Roof Tiles
The cracked roof tiles were repaired with Titebond sealant.



Building 15177: Identified Cracked Roof Tiles
Cracked roof tiles can allow premature underlayment deterioration from excessive UV exposure.



Building 15177: Repaired Cracked Roof Tiles
The cracked roof tiles were repaired with Titebond sealant.

Inspection Report

Livingston Lakes Condo, Naples, FL

Work Order #: 13028

Inspection Date: 06/13/2025




Building 15177: Identified Cracked Roof Tiles
Cracked roof tiles can allow premature underlayment deterioration from excessive UV exposure.



Building 15177: Repaired Cracked Roof Tiles
The cracked roof tiles were repaired with Titebond sealant.



Building 15177: Identified Cracked Roof Tiles
Cracked roof tiles can allow premature underlayment deterioration from excessive UV exposure.



Building 15177: Repaired Cracked Roof Tiles
The cracked roof tiles were repaired with Titebond sealant.

Inspection Report

Livingston Lakes Condo, Naples, FL

Work Order #: 13028

Inspection Date: 06/13/2025



Building 15177: Identified Cracked Roof Tiles

Cracked roof tiles can allow premature underlayment deterioration from excessive UV exposure.



Building 15177: Repaired Cracked Roof Tiles

The cracked roof tiles were repaired with Titebond sealant.



Building 15177: Identified Cracked Roof Tiles

Cracked roof tiles can allow premature underlayment deterioration from excessive UV exposure.



Building 15177: Repaired Cracked Roof Tiles

The cracked roof tiles were repaired with Titebond sealant.

Inspection Report

Livingston Lakes Condo, Naples, FL

Work Order #: 13028

Inspection Date: 06/13/2025



Building 15177: Identified Cracked Roof Tiles
Cracked roof tiles can allow premature underlayment deterioration from excessive UV exposure.



Building 15177: Repaired Cracked Roof Tiles
The cracked roof tiles were repaired with Titebond sealant.



Building 15177: Downspouts
The downspouts appear to be in good condition.



Building 15177: Downspouts
The downspouts appear to be in good condition.

Inspection Report

Livingston Lakes Condo, Naples, FL

Work Order #: 13028

Inspection Date: 06/13/2025



Building 15181
Building Identification



Building 15181: Surface Overview
The roof surface appears to be in good, maintainable condition at this time.



Building 15181: Appearance Overview
The roof appearance is in good, maintainable condition.



Building 15181: Surface Overview
The roof surface appears to be in good, maintainable condition at this time.

Inspection Report

Livingston Lakes Condo, Naples, FL

Work Order #: 13028

Inspection Date: 06/13/2025



Building 15181: Ridge Tiles

Ridge tiles appear to be in good condition.



Building 15181: Valley

The valley tiles appear to be in good condition.



Building 15181: Roof Vents

Roof vents appear to be in good condition.



Building 15181: Roof Vents

Roof vents appear to be in good condition.

Inspection Report

Livingston Lakes Condo, Naples, FL

Work Order #: 13028

Inspection Date: 06/13/2025



Building 15181: Lead Boots
Lead boots appear to be in good condition.



Building 15181: Lead Boots
Lead boots appear to be in good condition.



Building 15181: Gutters
The gutters appear to be in good condition.



Building 15181: Gutters
The gutters appear to be in good condition.

Inspection Report

Livingston Lakes Condo, Naples, FL

Work Order #: 13028

Inspection Date: 06/13/2025



Building 15181: Surface Overview - Lower Roof
The roof surface appears to be in good, maintainable condition at this time.



Building 15181: Appearance Overview - Lower Roof
The roof appearance is in good, maintainable condition.



Building 15181: Surface Overview - Lower Roof
The roof surface appears to be in good, maintainable condition at this time.



Building 15181: Appearance Overview - Lower Roof
The roof appearance is in good, maintainable condition.

Inspection Report

Livingston Lakes Condo, Naples, FL

Work Order #: 13028

Inspection Date: 06/13/2025



Building 15181: Displaced/Missing Roof Tile

Displaced or missing roof tiles can allow premature underlayment deterioration from excessive UV exposure and potential water intrusion.



Building 15181: Repaired Displaced/Missing Roof Tile

Replaced and secured the missing roof tile.



Building 15181: Identified Cracked Roof Tiles

Cracked roof tiles can allow premature underlayment deterioration from excessive UV exposure.



Building 15181: Repaired Cracked Roof Tiles

The cracked roof tiles were repaired with Titebond sealant.

Inspection Report

Livingston Lakes Condo, Naples, FL

Work Order #: 13028

Inspection Date: 06/13/2025



Building 15181: Identified Cracked Roof Tiles
Cracked roof tiles can allow premature underlayment deterioration from excessive UV exposure.



Building 15181: Repaired Cracked Roof Tiles
The cracked roof tiles were repaired with Titebond sealant.



Building 15181: Identified Cracked Roof Tiles
Cracked roof tiles can allow premature underlayment deterioration from excessive UV exposure.



Building 15181: Repaired Cracked Roof Tiles
The cracked roof tiles were repaired with Titebond sealant.

Inspection Report

Livingston Lakes Condo, Naples, FL

Work Order #: 13028

Inspection Date: 06/13/2025



Building 15181: Downspouts

The downspouts appear to be in good condition.



Building 15181: Downspouts

The downspouts appear to be in good condition.



Building 15184

Building Identification



Building 15184: Surface Overview

The roof surface appears to be in good, maintainable condition at this time.

Inspection Report

Livingston Lakes Condo, Naples, FL

Work Order #: 13028

Inspection Date: 06/13/2025



Building 15184: Appearance Overview
The roof appearance is in good, maintainable condition.



Building 15184: Appearance Overview
The roof appearance is in good, maintainable condition.



Building 15184: Ridge Tiles
Ridge tiles appear to be in good condition.



Building 15184: Valley
The valley tiles appear to be in good condition.

Inspection Report

Livingston Lakes Condo, Naples, FL

Work Order #: 13028

Inspection Date: 06/13/2025



Building 15184: Identified Cracked Roof Tiles
Cracked roof tiles can allow premature underlayment deterioration from excessive UV exposure.



Building 15184: Repaired Cracked Roof Tiles
The cracked roof tiles were repaired with Titebond sealant.



Building 15184: Displaced/Missing Roof Tile
Displaced or missing roof tiles can allow premature underlayment deterioration from excessive UV exposure and potential water intrusion.



Building 15184: Repaired Displaced/Missing Roof Tile
Replaced and secured the missing roof tile.

Inspection Report

Livingston Lakes Condo, Naples, FL

Work Order #: 13028

Inspection Date: 06/13/2025



Building 15184: Displaced/Missing Roof Tile

Displaced or missing roof tiles can allow premature underlayment deterioration from excessive UV exposure and potential water intrusion.



Building 15184: Repaired Displaced/Missing Roof Tile

Replaced and secured the missing roof tile.



Building 15184: Identified Cracked Roof Tiles

Cracked roof tiles can allow premature underlayment deterioration from excessive UV exposure.



Building 15184: Repaired Cracked Roof Tiles

The cracked roof tiles were repaired with Titebond sealant.

Inspection Report

Livingston Lakes Condo, Naples, FL

Work Order #: 13028

Inspection Date: 06/13/2025



Building 15184: Roof Vents
Roof vents appear to be in good condition.



Building 15184: Roof Vents
Roof vents appear to be in good condition.



Building 15184: Lead Boots
Lead boots appear to be in good condition.



Building 15184: Lead Boots
Lead boots appear to be in good condition.

Inspection Report

Livingston Lakes Condo, Naples, FL

Work Order #: 13028

Inspection Date: 06/13/2025



Building 15184: Gutters

The gutters appear to be in good condition.



Building 15184: Gutters

The gutters appear to be in good condition.



Building 15184: Surface Overview - Lower Roof

The roof surface appears to be in good, maintainable condition at this time.



Building 15184: Appearance Overview - Lower Roof

The roof appearance is in good, maintainable condition.

Inspection Report

Livingston Lakes Condo, Naples, FL

Work Order #: 13028

Inspection Date: 06/13/2025



Building 15184: Wall

The walls appear to be in good condition.



Building 15184: Appearance Overview - Lower Roof

The roof appearance is in good, maintainable condition.



Building 15184: Counter Flashings

The counter flashing appears to be in good condition.



Building 15184: Surface Overview - Lower Roof

The roof surface appears to be in good, maintainable condition at this time.

Inspection Report

Livingston Lakes Condo, Naples, FL

Work Order #: 13028

Inspection Date: 06/13/2025



Building 15184: Displaced/Missing Roof Tile

Displaced or missing roof tiles can allow premature underlayment deterioration from excessive UV exposure and potential water intrusion.



Building 15184: Repaired Displaced/Missing Roof Tile

Replaced and secured the missing roof tile.



Building 15184: Identified Cracked Roof Tiles

Cracked roof tiles can allow premature underlayment deterioration from excessive UV exposure.



Building 15184: Repaired Cracked Roof Tiles

The cracked roof tiles were repaired with Titebond sealant.

Inspection Report

Livingston Lakes Condo, Naples, FL

Work Order #: 13028

Inspection Date: 06/13/2025



Building 15184: Identified Cracked Roof Tiles
Cracked roof tiles can allow premature underlayment deterioration from excessive UV exposure.



Building 15184: Repaired Cracked Roof Tiles
The cracked roof tiles were repaired with Titebond sealant.



Building 15184: Identified Cracked Roof Tiles
Cracked roof tiles can allow premature underlayment deterioration from excessive UV exposure.



Building 15184: Repaired Cracked Roof Tiles
The cracked roof tiles were repaired with Titebond sealant.

Inspection Report

Livingston Lakes Condo, Naples, FL

Work Order #: 13028

Inspection Date: 06/13/2025



Building 15184: Identified Cracked Roof Tiles
Cracked roof tiles can allow premature underlayment deterioration from excessive UV exposure.



Building 15184: Repaired Cracked Roof Tiles
The cracked roof tiles were repaired with Titebond sealant.



Building 15184: Identified Cracked Roof Tiles
Cracked roof tiles can allow premature underlayment deterioration from excessive UV exposure.



Building 15184: Repaired Cracked Roof Tiles
The cracked roof tiles were repaired with Titebond sealant.

Inspection Report

Livingston Lakes Condo, Naples, FL

Work Order #: 13028

Inspection Date: 06/13/2025



Building 15184: Identified Cracked Roof Tiles
Cracked roof tiles can allow premature underlayment deterioration from excessive UV exposure.



Building 15184: Repaired Cracked Roof Tiles
The cracked roof tiles were repaired with Titebond sealant.



Building 15184: Identified Cracked Roof Tiles
Cracked roof tiles can allow premature underlayment deterioration from excessive UV exposure.



Building 15184: Repaired Cracked Roof Tiles
The cracked roof tiles were repaired with Titebond sealant.

Inspection Report

Livingston Lakes Condo, Naples, FL

Work Order #: 13028

Inspection Date: 06/13/2025



Building 15184: Downspout- missing
Downspout is missing.



Building 15184: Downspout- missing
The painting company that is painting the exteriors in Livingston Lakes has the missing downspouts.



Building 15185
Building Identification



Building 15185: Surface Overview
The roof surface appears to be in good, maintainable condition at this time.

Inspection Report

Livingston Lakes Condo, Naples, FL

Work Order #: 13028

Inspection Date: 06/13/2025



Building 15185: Appearance Overview

The roof appearance is in good, maintainable condition.



Building 15185: Surface Overview

The roof surface appears to be in good, maintainable condition at this time.



Building 15185: Ridge Tiles

Ridge tiles appear to be in good condition.



Building 15185: Valley

The valley tiles appear to be in good condition.

Inspection Report

Livingston Lakes Condo, Naples, FL

Work Order #: 13028

Inspection Date: 06/13/2025



Building 15185: Identified Cracked Roof Tiles
Cracked roof tiles can allow premature underlayment deterioration from excessive UV exposure.



Building 15185: Repaired Cracked Roof Tiles
The cracked roof tiles were repaired with Titebond sealant.



Building 15185: Displaced/Missing Roof Tile
Displaced or missing roof tiles can allow premature underlayment deterioration from excessive UV exposure and potential water intrusion.



Building 15185: Repaired Displaced/Missing Roof Tile
Replaced and secured the missing roof tile.

Inspection Report

Livingston Lakes Condo, Naples, FL

Work Order #: 13028

Inspection Date: 06/13/2025



Building 15185: Displaced/Missing Roof Tile

Displaced or missing roof tiles can allow premature underlayment deterioration from excessive UV exposure and potential water intrusion.



Building 15185: Repaired Displaced/Missing Roof Tile

Replaced and secured the missing roof tile.



Building 15185: Displaced/Missing Roof Tile

Displaced or missing roof tiles can allow premature underlayment deterioration from excessive UV exposure and potential water intrusion.



Building 15185: Repaired Displaced/Missing Roof Tile

Replaced and secured the missing roof tile.

Inspection Report

Livingston Lakes Condo, Naples, FL

Work Order #: 13028

Inspection Date: 06/13/2025



Building 15185: Displaced/Missing Roof Tile

Displaced or missing roof tiles can allow premature underlayment deterioration from excessive UV exposure and potential water intrusion.



Building 15185: Repaired Displaced/Missing Roof Tile

Replaced and secured the missing roof tile.



Building 15185: Identified Cracked Roof Tiles

Cracked roof tiles can allow premature underlayment deterioration from excessive UV exposure.



Building 15185: Repaired Cracked Roof Tiles

The cracked roof tiles were repaired with Titebond sealant.

Inspection Report

Livingston Lakes Condo, Naples, FL

Work Order #: 13028

Inspection Date: 06/13/2025



Building 15185: Identified Cracked Roof Tiles
Cracked roof tiles can allow premature underlayment deterioration from excessive UV exposure.



Building 15185: Repaired Cracked Roof Tiles
The cracked roof tiles were repaired with Titebond sealant.



Building 15185: Identified Cracked Roof Tiles
Cracked roof tiles can allow premature underlayment deterioration from excessive UV exposure.



Building 15185: Repaired Cracked Roof Tiles
The cracked roof tiles were repaired with Titebond sealant.

Inspection Report

Livingston Lakes Condo, Naples, FL

Work Order #: 13028

Inspection Date: 06/13/2025



Building 15185: Roof Vents
Roof vents appear to be in good condition.



Building 15185: Lead Boots
Lead boots appear to be in good condition.



Building 15185: Lead Boots
Lead boots appear to be in good condition.



Building 15185: Missing Mortar
Identified missing mortar around of lead boot. Crowther Roofing suggests installing mortar.

Inspection Report

Livingston Lakes Condo, Naples, FL

Work Order #: 13028

Inspection Date: 06/13/2025



Building 15185: Gutters

The gutters appear to be in good condition.



Building 15185: Gutters

The gutters appear to be in good condition.



Building 15185: Surface Overview - Lower Roof

The roof surface appears to be in good, maintainable condition at this time.



Building 15185: Appearance Overview - Lower Roof

The roof appearance is in good, maintainable condition.

Inspection Report

Livingston Lakes Condo, Naples, FL

Work Order #: 13028

Inspection Date: 06/13/2025



Building 15185: Surface Overview - Lower Roof
The roof surface appears to be in good, maintainable condition at this time.



Building 15185: Appearance Overview - Lower Roof
The roof appearance is in good, maintainable condition.



Building 15185: Identified Cracked Roof Tiles
Cracked roof tiles can allow premature underlayment deterioration from excessive UV exposure.



Building 15185: Repaired Cracked Roof Tiles
The cracked roof tiles were repaired with Titebond sealant.

Inspection Report

Livingston Lakes Condo, Naples, FL

Work Order #: 13028

Inspection Date: 06/13/2025



Building 15185: Wall

The walls appear to be in good condition.



Building 15185: Wall

The walls appear to be in good condition.



Building 15185: Downspout- missing

Downspout is missing. The painting company that is painting the exteriors in Livingston Lakes has the missing downspouts.



Building 15185: Downspout- missing

Downspout is missing.

Inspection Report

Livingston Lakes Condo, Naples, FL

Work Order #: 13028

Inspection Date: 06/13/2025



Building 15188
Building Identification



Building 15188: Surface Overview
The roof surface appears to be in good, maintainable condition at this time.



Building 15188: Appearance Overview
The roof appearance is in good, maintainable condition.




Building 15188: Surface Overview
The roof surface appears to be in good, maintainable condition at this time.

Inspection Report

Livingston Lakes Condo, Naples, FL

Work Order #: 13028

Inspection Date: 06/13/2025



Building 15188: Ridge Tiles
Ridge tiles appear to be in good condition.



Building 15188: Valley
The valley tiles appear to be in good condition.



Building 15188: Debris on Roof
Identified debris on the surface of the roof that could damage the membrane.



Building 15188: Broken Roof Tiles
Crowther Roofing suggests replacing 15 cracked roof tiles.

Inspection Report

Livingston Lakes Condo, Naples, FL

Work Order #: 13028

Inspection Date: 06/13/2025



Building 15188: Displaced/Missing Roof Tile

Displaced or missing roof tiles can allow premature underlayment deterioration from excessive UV exposure and potential water intrusion.



Building 15188: Repaired Displaced/Missing Roof Tile

Replaced and secured the missing roof tile.



Building 15188: Identified Cracked Roof Tiles

Cracked roof tiles can allow premature underlayment deterioration from excessive UV exposure.



Building 15188: Repaired Cracked Roof Tiles

The cracked roof tiles were repaired with Titebond sealant.

Inspection Report

Livingston Lakes Condo, Naples, FL

Work Order #: 13028

Inspection Date: 06/13/2025



Building 15188: Displaced/Missing Roof Tile

Displaced or missing roof tiles can allow premature underlayment deterioration from excessive UV exposure and potential water intrusion.



Building 15188: Repaired Displaced/Missing Roof Tile

Replaced and secured the missing roof tile.



Building 15188: Displaced/Missing Roof Tile

Displaced or missing roof tiles can allow premature underlayment deterioration from excessive UV exposure and potential water intrusion.



Building 15188: Repaired Displaced/Missing Roof Tile

Replaced and secured the missing roof tile.

Inspection Report

Livingston Lakes Condo, Naples, FL

Work Order #: 13028

Inspection Date: 06/13/2025



Building 15188: Roof Vents
Roof vents appear to be in good condition.



Building 15188: Roof Vents
Roof vents appear to be in good condition.



Building 15188: Lead Boots
Lead boots appear to be in good condition.



Building 15188: Lead Boots
Lead boots appear to be in good condition.

Inspection Report

Livingston Lakes Condo, Naples, FL

Work Order #: 13028

Inspection Date: 06/13/2025



Building 15188: Gutters

The gutters appear to be in good condition.



Building 15188: Gutters

The gutters appear to be in good condition.



Building 15188: Surface Overview - Lower Roof

The roof surface appears to be in good, maintainable condition at this time.



Building 15188: Appearance Overview - Lower Roof

The roof appearance is in good, maintainable condition.

Inspection Report

Livingston Lakes Condo, Naples, FL

Work Order #: 13028

Inspection Date: 06/13/2025



Building 15188: Wall

The walls appear to be in good condition.



Building 15188: Appearance Overview - Lower Roof

The roof appearance is in good, maintainable condition.



Building 15188: Identified Cracked Roof Tiles

Cracked roof tiles can allow premature underlayment deterioration from excessive UV exposure.



Building 15188: Repaired Cracked Roof Tiles

The cracked roof tiles were repaired with Titebond sealant.

Inspection Report

Livingston Lakes Condo, Naples, FL

Work Order #: 13028

Inspection Date: 06/13/2025



Building 15188: Displaced/Missing Roof Tile

Displaced or missing roof tiles can allow premature underlayment deterioration from excessive UV exposure and potential water intrusion.



Building 15188: Repaired Displaced/Missing Roof Tile

Replaced and secured the missing roof tile.



Building 15188: Identified Cracked Roof Tiles

Cracked roof tiles can allow premature underlayment deterioration from excessive UV exposure.



Building 15188: Repaired Cracked Roof Tiles

The cracked roof tiles were repaired with Titebond sealant.

Inspection Report


Livingston Lakes Condo, Naples, FL

Work Order #: 13028

Inspection Date: 06/13/2025



Building 15188: Identified Cracked Roof Tiles
Cracked roof tiles can allow premature underlayment deterioration from excessive UV exposure.



Building 15188: Repaired Cracked Roof Tiles
The cracked roof tiles were repaired with Titebond sealant.



Building 15188: Identified Cracked Roof Tiles
Cracked roof tiles can allow premature underlayment deterioration from excessive UV exposure.



Building 15188: Repaired Cracked Roof Tiles
The cracked roof tiles were repaired with Titebond sealant.

Inspection Report

Livingston Lakes Condo, Naples, FL

Work Order #: 13028

Inspection Date: 06/13/2025



Building 15188: Identified Cracked Roof Tiles
Cracked roof tiles can allow premature underlayment deterioration from excessive UV exposure.



Building 15188: Repaired Cracked Roof Tiles
The cracked roof tiles were repaired with Titebond sealant.



Building 15188: Identified Cracked Roof Tiles
Cracked roof tiles can allow premature underlayment deterioration from excessive UV exposure.



Building 15188: Repaired Cracked Roof Tiles
The cracked roof tiles were repaired with Titebond sealant.

Inspection Report

Livingston Lakes Condo, Naples, FL

Work Order #: 13028

Inspection Date: 06/13/2025



Building 15188: Counter Flashings

The counter flashing appears to be in good condition.



Building 15188: Downspout- missing

Downspout is missing. The painting company that is painting the exteriors in Livingston Lakes has the missing downspouts.



Building 15189
Building Identification



Building 15189: Surface Overview

The roof surface appears to be in good, maintainable condition at this time.

Inspection Report

Livingston Lakes Condo, Naples, FL

Work Order #: 13028

Inspection Date: 06/13/2025



Building 15189: Appearance Overview

The roof appearance is in good, maintainable condition.



Building 15189: Surface Overview

The roof surface appears to be in good, maintainable condition at this time.



Building 15189: Ridge Tiles

Ridge tiles appear to be in good condition.



Building 15189: Valley

The valley tiles appear to be in good condition.

Inspection Report

Livingston Lakes Condo, Naples, FL

Work Order #: 13028

Inspection Date: 06/13/2025



Building 15189: Identified Cracked Roof Tiles
Cracked roof tiles can allow premature underlayment deterioration from excessive UV exposure.



Building 15189: Repaired Cracked Roof Tiles
The cracked roof tiles were repaired with Titebond sealant.



Building 15189: Identified Cracked Roof Tiles
Cracked roof tiles can allow premature underlayment deterioration from excessive UV exposure.



Building 15189: Repaired Cracked Roof Tiles
The cracked roof tiles were repaired with Titebond sealant.

Inspection Report

Livingston Lakes Condo, Naples, FL

Work Order #: 13028

Inspection Date: 06/13/2025



Building 15189: Roof Vents
Roof vents appear to be in good condition.



Building 15189: Roof Vents
Roof vents appear to be in good condition.



Building 15189: Lead Boots
Lead boots appear to be in good condition.



Building 15189: Lead Boots
Lead boots appear to be in good condition.

Inspection Report

Livingston Lakes Condo, Naples, FL

Work Order #: 13028

Inspection Date: 06/13/2025



Building 15189: Gutters

The gutters appear to be in good condition.



Building 15189: Gutters

The gutters appear to be in good condition.



Building 15189: Surface Overview - Lower Roof

The roof surface appears to be in good, maintainable condition at this time.



Building 15189: Appearance Overview - Lower Roof

The roof appearance is in good, maintainable condition.

Inspection Report

Livingston Lakes Condo, Naples, FL

Work Order #: 13028

Inspection Date: 06/13/2025



Building 15189: Surface Overview - Lower Roof
The roof surface appears to be in good, maintainable condition at this time.



Building 15189: Surface Overview - Lower Roof
The roof surface appears to be in good, maintainable condition at this time.



Building 15189: Identified Cracked Roof Tiles
Cracked roof tiles can allow premature underlayment deterioration from excessive UV exposure.



Building 15189: Repaired Cracked Roof Tiles
The cracked roof tiles were repaired with Titebond sealant.

Inspection Report

Livingston Lakes Condo, Naples, FL

Work Order #: 13028

Inspection Date: 06/13/2025



Building 15189: Identified Cracked Roof Tiles

Cracked roof tiles can allow premature underlayment deterioration from excessive UV exposure.



Building 15189: Repaired Cracked Roof Tiles

The cracked roof tiles were repaired with Titebond sealant.



Building 15189: Identified Cracked Roof Tiles

Cracked roof tiles can allow premature underlayment deterioration from excessive UV exposure.



Building 15189: Repaired Cracked Roof Tiles

The cracked roof tiles were repaired with Titebond sealant.

Inspection Report

Livingston Lakes Condo, Naples, FL

Work Order #: 13028

Inspection Date: 06/13/2025



Building 15189: Identified Cracked Roof Tiles
Cracked roof tiles can allow premature underlayment deterioration from excessive UV exposure.



Building 15189: Repaired Cracked Roof Tiles
The cracked roof tiles were repaired with Titebond sealant.



Building 15189: Identified Cracked Roof Tiles
Cracked roof tiles can allow premature underlayment deterioration from excessive UV exposure.



Building 15189: Repaired Cracked Roof Tiles
The cracked roof tiles were repaired with Titebond sealant.

Inspection Report

Livingston Lakes Condo, Naples, FL

Work Order #: 13028

Inspection Date: 06/13/2025



Building 15189: Identified Cracked Roof Tiles
Cracked roof tiles can allow premature underlayment deterioration from excessive UV exposure.



Building 15189: Repaired Cracked Roof Tiles
The cracked roof tiles were repaired with Titebond sealant.



Building 15189: Identified Cracked Roof Tiles
Cracked roof tiles can allow premature underlayment deterioration from excessive UV exposure.



Building 15189: Repaired Cracked Roof Tiles
The cracked roof tiles were repaired with Titebond sealant.

Inspection Report

Livingston Lakes Condo, Naples, FL

Work Order #: 13028

Inspection Date: 06/13/2025



Building 15189: Counter Flashings

The counter flashing appears to be in good condition.



Building 15189: Wall

The walls appear to be in good condition.



Building 15189: Wall

The walls appear to be in good condition.



Building 15189: Downspout- missing

Downspout is missing. The painting company that is painting the exteriors in Livingston Lakes has the missing downspouts.

Inspection Report

Livingston Lakes Condo, Naples, FL

Work Order #: 13028

Inspection Date: 06/13/2025



Building 15193
Building Identification



Building 15193: Surface Overview
The roof surface appears to be in good, maintainable condition at this time.



Building 15193: Appearance Overview
The roof appearance is in good, maintainable condition.



Building 15193: Surface Overview
The roof surface appears to be in good, maintainable condition at this time.

Inspection Report

Livingston Lakes Condo, Naples, FL

Work Order #: 13028

Inspection Date: 06/13/2025



Building 15193: Ridge Tiles

Ridge tiles appear to be in good condition.



Building 15193: Valley

The valley tiles appear to be in good condition.



Building 15193: Identified Cracked Roof Tiles

Cracked roof tiles can allow premature underlayment deterioration from excessive UV exposure.



Building 15193: Repaired Cracked Roof Tiles

The cracked roof tiles were repaired with Titebond sealant.

Inspection Report

Livingston Lakes Condo, Naples, FL

Work Order #: 13028

Inspection Date: 06/13/2025



Building 15193: Displaced/Missing Roof Tile

Displaced or missing roof tiles can allow premature underlayment deterioration from excessive UV exposure and potential water intrusion.



Building 15193: Repaired Displaced/Missing Roof Tile

Replaced and secured the missing roof tile.



Building 15193: Roof Vents

Roof vents appear to be in good condition.



Building 15193: Roof Vents

Roof vents appear to be in good condition.

Inspection Report

Livingston Lakes Condo, Naples, FL

Work Order #: 13028

Inspection Date: 06/13/2025



Building 15193: Lead Boots
Lead boots appear to be in good condition.



Building 15193: Lead Boots
Lead boots appear to be in good condition.



Building 15193: Gutters
The gutters appear to be in good condition.



Building 15193: Gutters
The gutters appear to be in good condition.

Inspection Report

Livingston Lakes Condo, Naples, FL

Work Order #: 13028

Inspection Date: 06/13/2025



Building 15193: Surface Overview - Lower Roof
The roof surface appears to be in good, maintainable condition at this time.



Building 15193: Appearance Overview - Lower Roof
The roof appearance is in good, maintainable condition.



Building 15193: Surface Overview - Lower Roof
The roof surface appears to be in good, maintainable condition at this time.



Building 15193: Appearance Overview - Lower Roof
The roof appearance is in good, maintainable condition.

Inspection Report

Livingston Lakes Condo, Naples, FL

Work Order #: 13028

Inspection Date: 06/13/2025



Building 15193: Identified Cracked Roof Tiles
Cracked roof tiles can allow premature underlayment deterioration from excessive UV exposure.



Building 15193: Repaired Cracked Roof Tiles
The cracked roof tiles were repaired with Titebond sealant.



Building 15193: Identified Cracked Roof Tiles
Cracked roof tiles can allow premature underlayment deterioration from excessive UV exposure.



Building 15193: Repaired Cracked Roof Tiles
The cracked roof tiles were repaired with Titebond sealant.

Inspection Report

Livingston Lakes Condo, Naples, FL

Work Order #: 13028

Inspection Date: 06/13/2025



Building 15193: Identified Cracked Roof Tiles
Cracked roof tiles can allow premature underlayment deterioration from excessive UV exposure.



Building 15193: Repaired Cracked Roof Tiles
The cracked roof tiles were repaired with Titebond sealant.



Building 15193: Wall
The walls appear to be in good condition.



Building 15193: Downspout- missing
Downspout is missing. The painting company that is painting the exteriors in Livingston Lakes has the missing downspouts.

Inspection Report

Livingston Lakes Condo, Naples, FL

Work Order #: 13028

Inspection Date: 06/13/2025



Building 15197
Building Identification



Building 15197: Surface Overview
The roof surface appears to be in good, maintainable condition at this time.



Building 15197: Appearance Overview
The roof appearance is in good, maintainable condition.



Building 15197: Surface Overview
The roof surface appears to be in good, maintainable condition at this time.

Inspection Report

Livingston Lakes Condo, Naples, FL

Work Order #: 13028

Inspection Date: 06/13/2025



Building 15197: Ridge Tiles

Ridge tiles appear to be in good condition.



Building 15197: Valley

The valley tiles appear to be in good condition.



Building 15197: Identified Cracked Roof Tiles

Cracked roof tiles can allow premature underlayment deterioration from excessive UV exposure.



Building 15197: Repaired Cracked Roof Tiles

The cracked roof tiles were repaired with Titebond sealant.

Inspection Report

Livingston Lakes Condo, Naples, FL

Work Order #: 13028

Inspection Date: 06/13/2025



Building 15197: Identified Cracked Roof Tiles
Cracked roof tiles can allow premature underlayment deterioration from excessive UV exposure.



Building 15197: Repaired Cracked Roof Tiles
The cracked roof tiles were repaired with Titebond sealant.



Building 15197: Identified Cracked Roof Tiles
Cracked roof tiles can allow premature underlayment deterioration from excessive UV exposure.



Building 15197: Repaired Cracked Roof Tiles
The cracked roof tiles were repaired with Titebond sealant.

Inspection Report

Livingston Lakes Condo, Naples, FL

Work Order #: 13028

Inspection Date: 06/13/2025



Building 15197: Roof Vents

Roof vents appear to be in good condition.



Building 15197: Lead Boots

Lead boots appear to be in good condition.



Building 15197: Gutters

The gutters appear to be in good condition.



Building 15197: Gutters

The gutters appear to be in good condition.

Inspection Report

Livingston Lakes Condo, Naples, FL

Work Order #: 13028

Inspection Date: 06/13/2025



Building 15197: Surface Overview - Lower Roof
The roof surface appears to be in good, maintainable condition at this time.



Building 15197: Appearance Overview - Lower Roof
The roof appearance is in good, maintainable condition.



Building 15197: Appearance Overview - Lower Roof
The roof appearance is in good, maintainable condition.



Building 15197: Surface Overview - Lower Roof
The roof surface appears to be in good, maintainable condition at this time.

Inspection Report

Livingston Lakes Condo, Naples, FL

Work Order #: 13028

Inspection Date: 06/13/2025



Building 15197: Identified Cracked Roof Tiles
Cracked roof tiles can allow premature underlayment deterioration from excessive UV exposure.



Building 15197: Repaired Cracked Roof Tiles
The cracked roof tiles were repaired with Titebond sealant.



Building 15197: Identified Cracked Roof Tiles
Cracked roof tiles can allow premature underlayment deterioration from excessive UV exposure.



Building 15197: Repaired Cracked Roof Tiles
The cracked roof tiles were repaired with Titebond sealant.

Inspection Report

Livingston Lakes Condo, Naples, FL

Work Order #: 13028

Inspection Date: 06/13/2025



Building 15197: Identified Cracked Roof Tiles
Cracked roof tiles can allow premature underlayment deterioration from excessive UV exposure.



Building 15197: Repaired Cracked Roof Tiles
The cracked roof tiles were repaired with Titebond sealant.



Building 15197: Identified Cracked Roof Tiles
Cracked roof tiles can allow premature underlayment deterioration from excessive UV exposure.



Building 15197: Repaired Cracked Roof Tiles
The cracked roof tiles were repaired with Titebond sealant.

Inspection Report

Livingston Lakes Condo, Naples, FL

Work Order #: 13028

Inspection Date: 06/13/2025



Building 15197: Identified Cracked Roof Tiles

Cracked roof tiles can allow premature underlayment deterioration from excessive UV exposure.



Building 15197: Repaired Cracked Roof Tiles

The cracked roof tiles were repaired with Titebond sealant.



Building 15197: Identified Cracked Roof Tiles

Cracked roof tiles can allow premature underlayment deterioration from excessive UV exposure.



Building 15197: Repaired Cracked Roof Tiles

The cracked roof tiles were repaired with Titebond sealant.

Inspection Report

Livingston Lakes Condo, Naples, FL

Work Order #: 13028

Inspection Date: 06/13/2025



Building 15197: Counter Flashings

The counter flashing appears to be in good condition.



Building 15197: Downspout- missing

Downspout is missing. The painting company that is painting the exteriors in Livingston Lakes has the missing downspouts.



Building 15201
Building Identification



Building 15201: Surface Overview
The roof surface appears to be in good, maintainable condition at this time.

Inspection Report

Livingston Lakes Condo, Naples, FL

Work Order #: 13028

Inspection Date: 06/13/2025



Building 15201: Appearance Overview

The roof appearance is in good, maintainable condition.



Building 15201: Surface Overview

The roof surface appears to be in good, maintainable condition at this time.



Building 15201: Ridge Tiles

Ridge tiles appear to be in good condition.



Building 15201: Valley

The valley tiles appear to be in good condition.

Inspection Report

Livingston Lakes Condo, Naples, FL

Work Order #: 13028

Inspection Date: 06/13/2025



Building 15201: Identified Cracked Roof Tiles
Cracked roof tiles can allow premature underlayment deterioration from excessive UV exposure.



Building 15201: Repaired Cracked Roof Tiles
The cracked roof tiles were repaired with Titebond sealant.



Building 15201: Identified Cracked Roof Tiles
Cracked roof tiles can allow premature underlayment deterioration from excessive UV exposure.



Building 15201: Repaired Cracked Roof Tiles
The cracked roof tiles were repaired with Titebond sealant.

Inspection Report

Livingston Lakes Condo, Naples, FL

Work Order #: 13028

Inspection Date: 06/13/2025



Building 15201: Identified Cracked Roof Tiles

Cracked roof tiles can allow premature underlayment deterioration from excessive UV exposure.



Building 15201: Repaired Cracked Roof Tiles

The cracked roof tiles were repaired with Titebond sealant.



Building 15201: Identified Cracked Roof Tiles

Cracked roof tiles can allow premature underlayment deterioration from excessive UV exposure.



Building 15201: Repaired Cracked Roof Tiles

The cracked roof tiles were repaired with Titebond sealant.

Inspection Report

Livingston Lakes Condo, Naples, FL

Work Order #: 13028

Inspection Date: 06/13/2025



Building 15201: Identified Cracked Roof Tiles
Cracked roof tiles can allow premature underlayment deterioration from excessive UV exposure.



Building 15201: Repaired Cracked Roof Tiles
The cracked roof tiles were repaired with Titebond sealant.



Building 15201: Identified Cracked Roof Tiles
Cracked roof tiles can allow premature underlayment deterioration from excessive UV exposure.



Building 15201: Repaired Cracked Roof Tiles
The cracked roof tiles were repaired with Titebond sealant.

Inspection Report

Livingston Lakes Condo, Naples, FL

Work Order #: 13028

Inspection Date: 06/13/2025



Building 15201: Identified Cracked Roof Tiles
Cracked roof tiles can allow premature underlayment deterioration from excessive UV exposure.



Building 15201: Repaired Cracked Roof Tiles
The cracked roof tiles were repaired with Titebond sealant.



Building 15201: Identified Cracked Roof Tiles
Cracked roof tiles can allow premature underlayment deterioration from excessive UV exposure.



Building 15201: Repaired Cracked Roof Tiles
The cracked roof tiles were repaired with Titebond sealant.

Inspection Report

Livingston Lakes Condo, Naples, FL

Work Order #: 13028

Inspection Date: 06/13/2025



Building 15201: Identified Cracked Roof Tiles
Cracked roof tiles can allow premature underlayment deterioration from excessive UV exposure.



Building 15201: Repaired Cracked Roof Tiles
The cracked roof tiles were repaired with Titebond sealant.



Building 15201: Identified Cracked Roof Tiles
Cracked roof tiles can allow premature underlayment deterioration from excessive UV exposure.



Building 15201: Repaired Cracked Roof Tiles
The cracked roof tiles were repaired with Titebond sealant.

Inspection Report

Livingston Lakes Condo, Naples, FL

Work Order #: 13028

Inspection Date: 06/13/2025



Building 15201: Displaced/Missing Roof Tile

Displaced or missing roof tiles can allow premature underlayment deterioration from excessive UV exposure and potential water intrusion.



Building 15201: Repaired Displaced/Missing Roof Tile

Replaced and secured the missing roof tile.



Building 15201: Identified Cracked Roof Tiles

Cracked roof tiles can allow premature underlayment deterioration from excessive UV exposure.



Building 15201: Repaired Cracked Roof Tiles

The cracked roof tiles were repaired with Titebond sealant.

Inspection Report

Livingston Lakes Condo, Naples, FL

Work Order #: 13028

Inspection Date: 06/13/2025



Building 15201: Displaced/Missing Roof Tile

Displaced or missing roof tiles can allow premature underlayment deterioration from excessive UV exposure and potential water intrusion.



Building 15201: Repaired Displaced/Missing Roof Tile

Replaced and secured the missing roof tile.



Building 15201: Displaced/Missing Roof Tile

Displaced or missing roof tiles can allow premature underlayment deterioration from excessive UV exposure and potential water intrusion.



Building 15201: Repaired Displaced/Missing Roof Tile

Replaced and secured the missing roof tile.

Inspection Report

Livingston Lakes Condo, Naples, FL

Work Order #: 13028

Inspection Date: 06/13/2025



Building 15201: Displaced/Missing Roof Tile

Displaced or missing roof tiles can allow premature underlayment deterioration from excessive UV exposure and potential water intrusion.



Building 15201: Repaired Displaced/Missing Roof Tile

Replaced and secured the missing roof tile.



Building 15201: Roof Vents

Roof vents appear to be in good condition.



Building 15201: Lead Boots

Lead boots appear to be in good condition.

Inspection Report

Livingston Lakes Condo, Naples, FL

Work Order #: 13028

Inspection Date: 06/13/2025



Building 15201: Lead Boots
Lead boots appear to be in good condition.



Building 15201: Gutter Metal- Broken
Gutter is broken and needs to be replaced. (1ft.6" residential model).



Building 15201: Gutters
The gutters appear to be in good condition.



Building 15201: Gutters
The gutters appear to be in good condition.

Inspection Report

Livingston Lakes Condo, Naples, FL

Work Order #: 13028

Inspection Date: 06/13/2025



Building 15201: Surface Overview - Lower Roof
The roof surface appears to be in good, maintainable condition at this time.



Building 15201: Appearance Overview - Lower Roof
The roof appearance is in good, maintainable condition.



Building 15201: Surface Overview - Lower Roof
The roof surface appears to be in good, maintainable condition at this time.



Building 15201: Appearance Overview - Lower Roof
The roof appearance is in good, maintainable condition.

Inspection Report

Livingston Lakes Condo, Naples, FL

Work Order #: 13028

Inspection Date: 06/13/2025



Building 15201: Downspouts

The downspouts appear to be in good condition.



Building 15201: Downspouts

The downspouts appear to be in good condition.



Building 15205

Building Identification



Building 15205: Surface Overview

The roof surface appears to be in good, maintainable condition at this time.

Inspection Report

Livingston Lakes Condo, Naples, FL

Work Order #: 13028

Inspection Date: 06/13/2025



Building 15205: Appearance Overview

The roof appearance is in good, maintainable condition.



Building 15205: Surface Overview

The roof surface appears to be in good, maintainable condition at this time.



Building 15205: Ridge Tiles

Ridge tiles appear to be in good condition.



Building 15205: Valley

The valley tiles appear to be in good condition.

Inspection Report

Livingston Lakes Condo, Naples, FL

Work Order #: 13028

Inspection Date: 06/13/2025



Building 15205: Displaced/Missing Roof Tile

Displaced or missing roof tiles can allow premature underlayment deterioration from excessive UV exposure and potential water intrusion.



Building 15205: Repaired Displaced/Missing Roof Tile

Replaced and secured the missing roof tile.



Building 15205: Displaced/Missing Roof Tile

Displaced or missing roof tiles can allow premature underlayment deterioration from excessive UV exposure and potential water intrusion.



Building 15205: Repaired Displaced/Missing Roof Tile

Replaced and secured the missing roof tile.

Inspection Report

Livingston Lakes Condo, Naples, FL

Work Order #: 13028

Inspection Date: 06/13/2025



Building 15205: Identified Cracked Roof Tiles

Cracked roof tiles can allow premature underlayment deterioration from excessive UV exposure.



Building 15205: Repaired Cracked Roof Tiles

The cracked roof tiles were repaired with Titebond sealant.



Building 15205: Displaced/Missing Roof Tile

Displaced or missing roof tiles can allow premature underlayment deterioration from excessive UV exposure and potential water intrusion.



Building 15205: Repaired Displaced/Missing Roof Tile

Replaced and secured the missing roof tile.

Inspection Report

Livingston Lakes Condo, Naples, FL

Work Order #: 13028

Inspection Date: 06/13/2025



Building 15205: Displaced/Missing Roof Tile

Displaced or missing roof tiles can allow premature underlayment deterioration from excessive UV exposure and potential water intrusion.



Building 15205: Repaired Displaced/Missing Roof Tile

Replaced and secured the missing roof tile.



Building 15205: Displaced/Missing Roof Tile

Displaced or missing roof tiles can allow premature underlayment deterioration from excessive UV exposure and potential water intrusion.



Building 15205: Repaired Displaced/Missing Roof Tile

Replaced and secured the missing roof tile.

Inspection Report

Livingston Lakes Condo, Naples, FL

Work Order #: 13028

Inspection Date: 06/13/2025



Building 15205: Displaced/Missing Roof Tile

Displaced or missing roof tiles can allow premature underlayment deterioration from excessive UV exposure and potential water intrusion.



Building 15205: Repaired Displaced/Missing Roof Tile

Replaced and secured the missing roof tile.



Building 15205: Roof Vents

Roof vents appear to be in good condition.



Building 15205: Roof Vents

Roof vents appear to be in good condition.

Inspection Report

Livingston Lakes Condo, Naples, FL

Work Order #: 13028

Inspection Date: 06/13/2025



Building 15205: Lead Boots

Lead boots appear to be in good condition.



Building 15205: Lead Boots

Lead boots appear to be in good condition.



Building 15205: Gutters

The gutters appear to be in good condition.



Building 15205: Gutters

The gutters appear to be in good condition.

Inspection Report

Livingston Lakes Condo, Naples, FL

Work Order #: 13028

Inspection Date: 06/13/2025



Building 15205: Surface Overview - Lower Roof
The roof surface appears to be in good, maintainable condition at this time.



Building 15205: Appearance Overview - Lower Roof
The roof appearance is in good, maintainable condition.



Building 15205: Surface Overview - Lower Roof
The roof surface appears to be in good, maintainable condition at this time.



Building 15205: Appearance Overview - Lower Roof
The roof appearance is in good, maintainable condition.

Inspection Report

Livingston Lakes Condo, Naples, FL

Work Order #: 13028

Inspection Date: 06/13/2025



Building 15205: Identified Cracked Roof Tiles
Cracked roof tiles can allow premature underlayment deterioration from excessive UV exposure.



Building 15205: Repaired Cracked Roof Tiles
The cracked roof tiles were repaired with Titebond sealant.



Building 15205: Identified Cracked Roof Tiles
Cracked roof tiles can allow premature underlayment deterioration from excessive UV exposure.



Building 15205: Repaired Cracked Roof Tiles
The cracked roof tiles were repaired with Titebond sealant.

Inspection Report

Livingston Lakes Condo, Naples, FL

Work Order #: 13028

Inspection Date: 06/13/2025



Building 15205: Identified Cracked Roof Tiles
Cracked roof tiles can allow premature underlayment deterioration from excessive UV exposure.



Building 15205: Repaired Cracked Roof Tiles
The cracked roof tiles were repaired with Titebond sealant.



Building 15205: Loose Soffit
Identified 2-feet of loose soffit.



Building 15205: Completed Repair
Soffit was properly secured back into place.

Inspection Report

Livingston Lakes Condo, Naples, FL

Work Order #: 13028

Inspection Date: 06/13/2025



Building 15205: Loose Soffit
Identified 2-feet of loose soffit.



Building 15205: Completed Repair
Soffit was properly secured back into place.



Building 15205: Downspouts
The downspouts appear to be in good condition.



Building 15205: Downspouts
The downspouts appear to be in good condition.

Inspection Report

Livingston Lakes Condo, Naples, FL

Work Order #: 13028

Inspection Date: 06/13/2025



Building 15209
Building Identification



Building 15209: Surface Overview
The roof surface appears to be in good, maintainable condition at this time.



Building 15209: Appearance Overview
The roof appearance is in good, maintainable condition.



Building 15209: Surface Overview
The roof surface appears to be in good, maintainable condition at this time.

Inspection Report

Livingston Lakes Condo, Naples, FL

Work Order #: 13028

Inspection Date: 06/13/2025



Building 15209: Ridge Tiles

Ridge tiles appear to be in good condition.



Building 15209: Valley

The valley tiles appear to be in good condition.



Building 15209: Identified Cracked Roof Tiles

Cracked roof tiles can allow premature underlayment deterioration from excessive UV exposure.



Building 15209: Repaired Cracked Roof Tiles

The cracked roof tiles were repaired with Titebond sealant.

Inspection Report

Livingston Lakes Condo, Naples, FL

Work Order #: 13028

Inspection Date: 06/13/2025



Displaced/Missing Roof Tile

Displaced or missing roof tiles can allow premature underlayment deterioration from excessive UV exposure and potential water intrusion.



Repaired Displaced/Missing Roof Tile

Replaced and secured the missing roof tile.



Building 15209: Identified Cracked Roof Tiles

Cracked roof tiles can allow premature underlayment deterioration from excessive UV exposure.



Building 15209: Repaired Cracked Roof Tiles

The cracked roof tiles were repaired with Titebond sealant.

Inspection Report

Livingston Lakes Condo, Naples, FL

Work Order #: 13028

Inspection Date: 06/13/2025



Building 15209: Roof Vents
Roof vents appear to be in good condition.



Building 15209: Roof Vents
Roof vents appear to be in good condition.



Building 15209: Lead Boots
Lead boots appear to be in good condition.



Building 15209: Lead Boots
Lead boots appear to be in good condition.

Inspection Report

Livingston Lakes Condo, Naples, FL

Work Order #: 13028

Inspection Date: 06/13/2025



Building 15209: Gutters

The gutters appear to be in good condition.



Building 15209: Gutters

The gutters appear to be in good condition.



Building 15209: Surface Overview - Lower Roof

The roof surface appears to be in good, maintainable condition at this time.



Building 15209: Appearance Overview - Lower Roof

The roof appearance is in good, maintainable condition.

Inspection Report

Livingston Lakes Condo, Naples, FL

Work Order #: 13028

Inspection Date: 06/13/2025



Building 15209: Surface Overview - Lower Roof
The roof surface appears to be in good, maintainable condition at this time.



Building 15209: Appearance Overview - Lower Roof
The roof appearance is in good, maintainable condition.



Building 15209: Identified Cracked Roof Tiles
Cracked roof tiles can allow premature underlayment deterioration from excessive UV exposure.



Building 15209: Repaired Cracked Roof Tiles
Repaired cracked roof tiles with M1 sealant

Inspection Report

Livingston Lakes Condo, Naples, FL

Work Order #: 13028

Inspection Date: 06/13/2025



Building 15209: Downspouts
The downspouts appear to be in good condition.



Building 15209: Downspouts
The downspouts appear to be in good condition.



Building 15213
Building Identification



Building 15213: Surface Overview
The roof surface appears to be in good, maintainable condition at this time.

Inspection Report

Livingston Lakes Condo, Naples, FL

Work Order #: 13028

Inspection Date: 06/13/2025



Building 15213: Appearance Overview

The roof appearance is in good, maintainable condition.



Building 15213: Surface Overview

The roof surface appears to be in good, maintainable condition at this time.



Building 15213: Ridge Tiles

Ridge tiles appear to be in good condition.



Building 15213: Valley

The valley tiles appear to be in good condition.

Inspection Report

Livingston Lakes Condo, Naples, FL

Work Order #: 13028

Inspection Date: 06/13/2025



Building 15213: Roof Vents

Roof vents appear to be in good condition.



Building 15213: Roof Vents

Roof vents appear to be in good condition.



Building 15213: Lead Boots

Lead boots appear to be in good condition.



Building 15213: Lead Boots

Lead boots appear to be in good condition.

Inspection Report

Livingston Lakes Condo, Naples, FL

Work Order #: 13028

Inspection Date: 06/13/2025



Building 15213: Surface Overview - Lower Roof
The roof surface appears to be in good, maintainable condition at this time.



Building 15213: Appearance Overview - Lower Roof
The roof appearance is in good, maintainable condition.



Building 15213: Surface Overview - Lower Roof
The roof surface appears to be in good, maintainable condition at this time.



Building 15213: Appearance Overview - Lower Roof
The roof appearance is in good, maintainable condition.

Inspection Report

Livingston Lakes Condo, Naples, FL

Work Order #: 13028

Inspection Date: 06/13/2025



Building 15213: Wall

The walls appear to be in good condition.



Building 15213: Counter Flashings

The counter flashing appears to be in good condition.



Building 15213: Displaced/Missing Roof Tile

Displaced or missing roof tiles can allow premature underlayment deterioration from excessive UV exposure and potential water intrusion.



Building 15213: Repaired Displaced/Missing Roof Tile

Replaced and secured the missing roof tile.

Inspection Report

Livingston Lakes Condo, Naples, FL

Work Order #: 13028

Inspection Date: 06/13/2025



Building 15213: Displaced/Missing Roof Tile

Displaced or missing roof tiles can allow premature underlayment deterioration from excessive UV exposure and potential water intrusion.



Building 15213: Repaired Displaced/Missing Roof Tile

Replaced and secured the missing roof tile.



Building 15213: Displaced/Missing Roof Tile

Displaced or missing roof tiles can allow premature underlayment deterioration from excessive UV exposure and potential water intrusion.



Building 15213: Repaired Displaced/Missing Roof Tile

Replaced and secured the missing roof tile.

Inspection Report

Livingston Lakes Condo, Naples, FL

Work Order #: 13028

Inspection Date: 06/13/2025



Building 15213: Displaced/Missing Roof Tile

Displaced or missing roof tiles can allow premature underlayment deterioration from excessive UV exposure and potential water intrusion.



Building 15213: Repaired Displaced/Missing Roof Tile

Replaced and secured the missing roof tile.



Building 15213: Identified Cracked Roof Tiles

Cracked roof tiles can allow premature underlayment deterioration from excessive UV exposure.



Building 15213: Repaired Cracked Roof Tiles

Repaired cracked roof tiles with M1 sealant

Inspection Report

Livingston Lakes Condo, Naples, FL

Work Order #: 13028

Inspection Date: 06/13/2025



Building 15213: Displaced/Missing Roof Tile

Displaced or missing roof tiles can allow premature underlayment deterioration from excessive UV exposure and potential water intrusion.



Building 15213: Repaired Displaced/Missing Roof Tile

Replaced and secured the missing roof tile.



Building 15213: Identified Cracked Roof Tiles

Cracked roof tiles can allow premature underlayment deterioration from excessive UV exposure.



Building 15213: Repaired Cracked Roof Tiles

Repaired cracked roof tiles with M1 sealant

Inspection Report

Livingston Lakes Condo, Naples, FL

Work Order #: 13028

Inspection Date: 06/13/2025



Building 15213: Displaced/Missing Roof Tile

Displaced or missing roof tiles can allow premature underlayment deterioration from excessive UV exposure and potential water intrusion.



Building 15213: Repaired Displaced/Missing Roof Tile

Replaced and secured the missing roof tile.



Building 15213: Downspouts

The downspouts appear to be in good condition.



Building 15213: Downspouts

The downspouts appear to be in good condition.