Pond Guru Fort Myers
P.O. Box 3439,
North Fort Myers, FL 33918,
(239) 997-8872

Service Report
REP-881

Contact Details

Company	:	Livingston Lakes Condo Association
Contact	:	Sarah Mackedanz
Service Address	:	15090 Palmer Lake Circle Naples, Florida 34109
Email	:	committee@livingstonlakescondo.com

Service Details

	:	WO806
Technician Involved	:	Troy Hardy, Devin Crosbie CM23704
Scheduled Start Time	:	Oct 26, 2026 08:00 AM
Checked in with	:	
Equipment Used	:	
Type	:	Asset Maintenance

Attachments

No records found

Jobsheet Details

Details/AM0035

Job Sheet Name	:	AM0035
Description	:	Aerator Maintenance
Number of Aerators Maintained	:	2
Type and Location of Aerators	:	Aquamaster
Aerator Notes / Issues Encountered	:	A1-A2, Lake 1
Aerator parts replaced	:	Filter 510151
All units debris and weeds cleared from cabinet?	:	Yes
All units cabinets cleaned and inspected?	:	Yes
All units prefilter/box intake inspected?	:	Yes
All units air filter inspected?	:	Yes
Maintained Aerator Photos	:	

Comments	:	A1-A2 one fan isn't working but still ok to run, unit is not on gfci Aerator compressor box in lake 1 has a fan not working, turned off. Repair quote to be sent.

Details/AM0069

Job Sheet Name	:	AM0069
Description	:	Fountain Maintenance
Number of Fountains Maintained	:	6
Type and Location of Fountains Maintained	:	Butler, Palmer, and Pocket Lakes
Fountain Notes/Issued Encountered	:	P2-F1
All units cleaned and inspected?	:	Yes
All units lights operating properly?	:	Yes
All units GFCI operating properly?	:	Yes
All units timers checked and set?	:	Yes
Maintained Fountain photos	:	
Comments	:	P2 Replace battery motor and light Unit didn't restart after service check power in / bad check connection / loose neutral on incoming power / unsecured seal tight + exposed wires recommend fitting a j box and securing flex conduit / connection may have pulled out due to this. F1 control panel inside door falls out, general condition poor, advise replacement of panel.