



July 14th, 2025

Livingston Lakes – Garden Homes
File # 25RN-0060
Walkthrough
Monday, July 14th, 2025
Page 1 of 10

ATTENDEES:

Anthony DiNardo

Karins Engineering Group (KEG)

Coach Homes 15184 and 15188				
Item	Description	Area	Photo	Completed Date
A	Chipped paint on garage door	15184: Unit 202	1	TBD
B	Excess paint on pavers	15184: South side	2	TBD
C	Painter's tape left on window	15184: Ground level east side window of stack 2	3	TBD
D	Excess spray paint from pipe	15184: North side exterior wall	4	TBD
E	Paint application pending on garage doors	15188: All units	5	TBD
F	Excess paint on pavers	15188: South side	6	TBD
G	Excess paint on screen mesh	15188: Ground level, south side	7	TBD

Very truly yours,
KARINS ENGINEERING GROUP, INC.



Photo 1



Photo 2



Photo 3



Photo 4



Photo 5



Photo 6



Photo 7

If any important issues from this walkthrough have not been covered in the above or are inconsistent with the understanding of the participants, please address these issues in writing to KEG within five (5) business days from the date of this letter. KEG trusts that this information is helpful. Should questions arise, please do not hesitate to call.

Sincerely,

Anthony DiNardo

Karins Engineering Group, Inc.

Anthony DiNardo, E.I.

Project Engineer