



Pond Guru Fort Myers

P.O. Box 3439,
North Fort Myers, FL 33918,
(239) 997-8872

Service Report

REP-473

Contact Details

Company	:	Livingston Lakes Condo Association
Contact	:	Sarah Mackedanz
Service Address	:	15090 Palmer Lake Circle Naples, Florida 34109
Email	:	committee@livingstonlakescondo.com

Service Details

	:	WO565
Technician Involved	:	Adi Long CM500152
Scheduled Start Time	:	Jul 17, 2026 07:30 AM
Checked in with	:	None
Equipment Used	:	Boat
Type	:	Asset Maintenance

Attachments

No records found

Jobsheet Details

Details/AM0016

Job Sheet Name	:	AM0016
Description	:	Aerator Maintenance Checked and cleaned units All operational
Number of Aerators Maintained	:	2
Type and Location of Aerators	:	
Aerator Notes / Issues Encountered	:	
Aerator parts replaced	:	
All units debris and weeds cleared from cabinet?	:	Yes
All units cabinets cleaned and inspected?	:	Yes
All units prefilter/box intake inspected?	:	Yes

All units air filter inspected?	:	Yes
Maintained Aerator Photos	:	
Comments	:	
Details/AM0040		
Job Sheet Name	:	AM0040
Description	:	Fountain Maintenance Checked and cleaned fountains and lights All units operational except P1 that is down for repairs.
Number of Fountains Maintained	:	5
Type and Location of Fountains Maintained	:	Aquamaster
Fountain Notes/Issued Encountered	:	
All units cleaned and inspected?	:	Yes
All units lights operating properly?	:	Yes
All units GFCI operating properly?	:	Yes
All units timers checked and set?	:	Yes
Maintained Fountain photos	:	
Comments	:	